


42

B1-01 PCM(F)



HARNESS SYMBOL:  (F)  (E)  (R)

[GRAY]
PCM
B1-01

(1)-(R)
X-09

[GRAY]
(F)-(R)
X-07

X-09
(1)-(R)