


# INSTRUMENT CLUSTER

C-a



52

|                                   |                                    |  |  |
|-----------------------------------|------------------------------------|--|--|
| <p>C-01 INSTRUMENT CLUSTER(I)</p> | <p>C-02 KEY REMINDER SWITCH(I)</p> | <p>C-03 IGNITION KEY ILLUMINATION(I)</p> |  |
|                                   |                                    |  |  |

HARNESS SYMBOL:  (F)  (E)  (R)

